

SUBJECT: Audit of Potable and Nonpotable Water in Iraq (Project Number D2006-D000LQ-0254)

organizations did not coordinate their oversight efforts. TB MED 577 requires command surgeons to oversee the implementation of Preventive Medicine instruction and procedures to achieve the established water quality standards. Preventive Medicine personnel are responsible for providing oversight of field water operations and for preventing waterborne illness and disease. DCMA is responsible for oversight of the contractor operations. We reviewed MNC-I Preventive Medicine records of the water operation sites that we visited. Preventive Medicine personnel provided monthly oversight visits to the three KBR water operation sites that we visited. However, they did not provide consistent oversight visits to the military water operation sites.

RECOMMENDATION 3:

We recommend that the Commander, Defense Contract Management Agency – Iraq establish a process to collaborate and share information and results from water operation oversight efforts with the MNC–I Command Surgeon, Preventive Medicine.

DCMA COMMENTS: Concur. The DCMA I/A Commander will establish a process to collaborate and share information with MNC–I Command Surgeon, Preventive Medicine.